

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

25X1A

## Approved For Release 2000/05/05 : CIA-RDP71B00590B000200100014-9

IN 55768

9939

SECRET

PAGE 2

IMPACT OCCURRED AS THE LEAD AIRCRAFT PASSED THE GCA MINIMUM ALTITUDE

ON THE GLIDE PATH.

- 2. ADDITIONAL FINDING: THE UNIT SOP FOR CHASE ACTIVITIES DOES NOT DIFFERENTIATE BETWEEN DAY AND NIGHT CHASE PROCEDURES.
- 3. ADDITIONAL FINDINGS NOT RELATED TO THE ACCIDENT:
  A BUCKING BAR, USED WHILE RIVETING SHEET METAL, WAS FOUND AT THE ACCIDENT SCENE. THIS AIRCRAFT HAD BEEN THROUGH PERIODIC INSPECTION AT OOAMA IN JUNE 1967. NO SHEET METAL WORK HAS BEEN PERFORMED ON THIS AIRCRAFT SINCE THAT TIME.

RECOMMENDATIONS:

- 1. THAT ALL PILOTS BE BRIEFED ON THE IMPORTANCE OF
  ADHEPING TO THE PUBLISHED SOP FOR CHASE ACTIVITIES WHICH PROHIBITS
  CHASE BELOW 500 FEET.
- 2. THAT THE CHASE SOP BE AMENDED TO PROHIBIT CHASE DURING DARKNESS EXCEPT IN CASE OF EMERGENCIES.
- 3. THAT AFROR INFORM COAMA OF THE FOREIGN OBJECT FOUND AT THE ACCIDENT SCENE.

R. N/A.

S. ALL PILOTS HAVE BEEN BRIEFED ON CHASE SOP. NIGHT CHASE REQUIRE-

T. N/A.

U. TDP REQUESTED ON ENGINES, STABILATOR ACTUATOR AND TRIM ACTUATORS.

V. PILOT DESCENDED BELOW 500 FOOT

SECDET

WHILE IN CHASE POSITION.

W. N/A.

X. N/A

25X1A

25X1A

Y. BOARD RECORDER, 3207.
Approved For Release 2000/05/05: CIA-RDP71B00590R000200100014-9
S E C R E T TOF: 051825Z OCT 67